

**Oil Absorption Value  
(EN ISO 787-5:1995 mod.)**

<b>Client</b>	LEFKON Marble Quarrying & Trading 3 Ifestou St. Maroussi - Athens 151 24 GREECE Tel: +30 210 6197745, E-mail: lefkon@lefkon.eu	<b>Report No</b>	2016/223
		<b>Date</b>	07-03-17
		<b>Issue</b>	0
<b>Project</b>	Natural Stone Laboratory Testing: "Lefkon Marble"	<b>Project No</b>	010217-E1

Sample description:	"Lefkon Marble"	Sample No	220217-1
Sampling date:	Feb-17	Receiving date:	22-02-17
Sampling site:	Xylalogo Quarry, 59 100 Veria, Greece	Testing date:	03-03-17
Sampling execution:	Client		

**Data**

<b>Specimen</b>			<b>No1</b>	<b>No2</b>
Dry mass	<i>m</i>	<i>g</i>	100.60	101.30
Linseed oil volume	<i>V</i>	<i>ml</i>	0.135	0.170
<i>Oil absorption value</i>	OA	<i>ml/100g</i>	0.13	0.17
<i>Oil absorption value</i>	OA	<i>g/100g</i>	0.12	0.16

**Result**

<i>Oil absorption value</i>	OA	<i>ml/100g</i>	0.2
<i>Oil absorption value</i>	OA	<i>g/100g</i>	0.1